

## 2. Possible Causes

DTC	Inspection Strategy	Setting Condition (Control Strategy)	Faulty Area
P1790	Hardware Circuit Inspection	• After ignition, the software detects invalid driver expected torque signal for 0.1 s or more and judges as malfunction by DTC	<ul style="list-style-type: none"> <li>• ABS/ESP</li> <li>• Wiring harness and connector (CAN communication system)</li> </ul>
P1735		• After ignition, the software detects that CAN signal frame of EPS is missing for 0.1 s or more and judges as malfunction by DTC	
U2091		• After ignition, the software detects that CAN signal frame of EPS is missing for 0.1 s or more and judges as malfunction by DTC	
P1795		• After ignition, the software detects implausible engine torque signal for 0.1 s or more and judges as malfunction by DTC	
P1796		• After ignition, the software detects implausible friction torque signal for 0.1 s or more and judges as malfunction by DTC	
P1798		• After ignition, the software detects implausible friction torque signal for 0.1 s or more and judges as malfunction by DTC	
P1799		• After ignition, the software detects invalid engine speed signal for 0.1 s or more and judges as malfunction by DTC	
P1801		• After ignition, the software detects invalid engine target idling signal for 0.1 s or more and judges as malfunction by DTC	
P1803		• After ignition, the software detects invalid accelerator pedal position signal for 0.1 s or more and judges as malfunction by DTC	
P1805		• After ignition, the software detects invalid engine coolant temperature signal for 0.1 s or more and judges as malfunction by DTC	
P1807		• After ignition, the software detects invalid ESP vehicle speed signal for 0.1 s or more and judges as malfunction by DTC	

DTC	Inspection Strategy	Setting Condition (Control Strategy)	Faulty Area
P1808	Hardware Circuit Inspection	<ul style="list-style-type: none"> <li>After ignition, the software detects implausible ESP vehicle speed signal for 0.1 s or more and judges as malfunction by DTC</li> </ul>	<ul style="list-style-type: none"> <li>ABS/ESP</li> <li>Wiring harness and connector (CAN communication system)</li> </ul>
P1810		<ul style="list-style-type: none"> <li>After ignition, the software detects invalid ESP left rear wheel speed signal for 0.1 s or more and judges as malfunction by DTC</li> </ul>	
P1811		<ul style="list-style-type: none"> <li>After ignition, the software detects implausible ESP left rear wheel speed signal for 0.1 s or more and judges as malfunction by DTC</li> </ul>	
P1813		<ul style="list-style-type: none"> <li>After ignition, the software detects invalid ESP right rear wheel speed signal for 0.1 s or more and judges as malfunction by DTC</li> </ul>	
P1814		<ul style="list-style-type: none"> <li>After ignition, the software detects implausible ESP right rear wheel speed signal for 0.1 s or more and judges as malfunction by DTC</li> </ul>	
P1816		<ul style="list-style-type: none"> <li>After ignition, the software detects invalid ESP left front wheel speed signal for 0.1 s or more and judges as malfunction by DTC</li> </ul>	
P1817		<ul style="list-style-type: none"> <li>After ignition, the software detects implausible ESP left front wheel speed signal for 0.1 s or more and judges as malfunction by DTC</li> </ul>	
P1819		<ul style="list-style-type: none"> <li>After ignition, the software detects invalid ESP right front wheel speed signal for 0.1 s or more and judges as malfunction by DTC</li> </ul>	
P1820		<ul style="list-style-type: none"> <li>After ignition, the software detects implausible ESP right front wheel speed signal for 0.1 s or more and judges as malfunction by DTC</li> </ul>	
P1824		<ul style="list-style-type: none"> <li>After ignition, the software detects CAN bus off for 0.1 s or more and judges as malfunction by DTC</li> </ul>	

### 3. Diagnosis Procedure

Test Conditions	Details/Results/Actions
1. General inspection	
	<p>A. Inspect each relative wiring harness connector for reliability, falling off, damage, poor contact, aging and looseness, etc.</p> <p>Is it normal?</p> <p><b>Yes</b></p> <p>Go to step 2.</p> <p><b>No</b></p> <p>Repair the faulty area.</p>
2. Clear DTC	
	<p>A. Connect the diagnostic tool.</p> <p>B. Clear DTC with diagnostic tool.</p> <p>C. Shake, pull and press diagnostic connector, EPS/ ABS control module, automatic transmission control module and engine control module wiring harness connector.</p> <p>D. Perform DTC diagnosis again using diagnostic tool.</p> <p>Are there DTC P1790, P1735, U2091, P1795, P1798, P1799, P1801, P1803, P1805, P1807, P1808, P1810, P1811, P1813, P1814, P1816, P1817, P1819, P1820, P1824?</p> <p><b>Yes</b></p> <p>Go to step 3.</p> <p><b>No</b></p> <p>Clear the DTC.</p>
3. Inspect and repair CAN bus circuit	
	<p>A. Inspect and repair CAN bus circuit.</p> <p><b>Refer to: CAN Bus Integrity Inspection (4.3.14 On-board Network System, Description and Operation)</b></p>