

ANDINA MOTOR'S, C.A.
SERV | CHANGAN

J-50084357-7

Página 1 de 1
Fecha: 03/09/2024
Hora: 03:54 pm
NUMA ANTONIO BOSCA

ORDEN DE REPARACION

Orden de Servicio Nro. S1 - 3839

Procedencia : Garantía Planta Emisión : 03/09/2024 15:52:20 Prometido : 03/09/2024 19:00:00

Cliete : SARA GUERRERO DE GARCIA Ced/Rif : V-4629797

Tifs.: MOV (0424) 7758672

Modelo : CS15 - CS15

Carrocería: LS5A3DSE1PD911210 Motor: N3CV514256 Placa: AB459UR

Kmts.: 3531 Fecha Venta: 01/03/2024 Color: ROJO Año: 2023


Asesor : NUMA ANTONIO BOSCA RONDÓN

Tifs.:

Tipo	Código	Descripción	Cantidad
<u>Garantía Planta</u>			
<u>Repuestos</u>			
REP	1106100-AB01	CONJUNTO BOMBA DE COMBUSTIBLE CS15	1,00
<u>Mano de Obra</u>			
MO	B51103005	CONJUNTO DE SOPORTE Y BOMBA DE COMBUSTIB	0,50

Percepción del Cliente

VEHICULO NO ENCIENDE




TECNICO: Dyhan Ascencio

Asesor de Servicio o Garantía

Aprobado por el cliente

FIRMA: _____





1450

P

33°C

H

0 Km/h

0.7
x1000r/min

F

E

C

AVG

8.1 L/100km

ODO

3531 km

CHONGQING CHANGAN AUTOMOBILE CO., LTD

VIN:LS5A3DSE1PD911210

Trademark Changan

Model SC7159ADB5

Engine Model JL473QF Net power 74.5kW

Piston displacement 1480mL

Total mass 1610kg

Manufacture date 2022-06-21 Seats 5



WARNING
ATTENTION

SRS SIDE AIRBAG



请勿依靠在车门上，以防侧边安全气囊充气膨胀时造成伤亡或重伤。

详细说明请参阅驾驶员手册。Do not lean against the door to avoid potential death or serious injury when the side airbag inflates.

See owner's manual for details.





