



PROSTAR



VCI-9030085921 connected



› Changan Passenger Vehicle › Fuel Vehicle › Hunter › Hunter_VIA › EMS[Diesel V

P0088F0 maximum rail pressure exceeded History DTC ●

P068A00 Early opening defect of main relay History DTC