

BOSCH

VCI-9030085921 connected

Changan Passenger Vehicle > Fuel Vehicle > Hunter > Hunter_VM > EMS[Diesel VM_2.5T_EURO5] > Diagnosis Data

0087F2 maximum positive deviation of rail pressure exceeded History DTC

1092F5 maximum positive deviation of rail pressure exceeded concerning set flow of fuel History DTC

008700 minimum rail pressure exceeded History DTC