

ORDEN DE REPARACION
J-50084357-7
SERV | CHANGAN
ANDINA MOTORS, C.A.

Fecha: 27/08/2024
 Hora: 08:38 pm
 MIAA ANTONIO MICO

Orden de Servicio No.: S1 - 3788
 Emision: 27/08/2024 16:38:32 Pionetido: 27/08/2024 19:00:00
 Tls: MOV 604741755281 DOM: 604741755281

Cliente: JUAN CARLOS VERGARA SANTANA CeaRif: V-19404501
 Modelo: NEW ALSVIN AT - NEW ALSVIN AT
 Camarceria: LS5A2ASE5PD914094 Motor: N3C7516331 Placa: AC273FL
 Kmils: 16178 Fecha Venta: 27/09/2023 Color: BLANCO Año: 2023
 Asesor: NUMA ANTONIO BOSCAN RONDON

Percepcion del Cliente
 Tipo: Código Descripción
 Cantidad **GARANTIA PLANTA**

KEY LUZ DE MOTOR

ANDINA MIAA ANTONIO MICO

Asesor de Servicio o Garantía
 Apoyado por el cliente



VE: 405066427 connected

Fuel Vehicle - ALSVIN Series - New ALSVIN - UAES (IP6) - Diagnostics Data Version - Actual Values - Diagnostics data 2

Sorti...	Name	Result	Unit
	lambda controller output	1.008	
	number of misfire: cylinder#1	46	
	number of misfire: cylinder#2	52	
	number of misfire: cylinder#3	56	
	number of misfire: cylinder#4	44	
	O2 sensor voltage bank1, sensor 1	1.675	V
	O2 sensor voltage bank1, sensor 2	0.742	V

Home Print Compare Capture Record Return

