

VCI-9090126821connected

CHANGAN(V2.95) > CHANGAN > Hunter > Hunter\_VM > EMS[Diesel VM\_2.5T\_EURO5] > Diagnosis Data Version > Read DTC

P0087F2 maximum positive deviation of rail pressure exceeded History DTC

Freeze frame

P1092F5 maximum positive deviation of rail pressure exceeded concerning set flow of fuel History DTC

Freeze frame

P008700 minimum rail pressure exceeded History DTC

Freeze frame

P0088F0 maximum rail pressure exceeded History DTC

Freeze frame

P033629 DFC for crankshaft signal diagnose disturbed signal History DTC

Freeze frame



Home



Print



Refresh



Clear



Return

