



VCI-9090126821 connected

CHANGAN(V2.95) > CHANGAN > Hunter > Hunter_VM > EMS(Diesel VM_2.5T_EUR05) > Diagnosis Data Version > Read DTC

P0087F2 maximum positive deviation of rail pressure exceeded Current DTC

P1092F5 maximum positive deviation of rail pressure exceeded concerning set flow of fuel Current DTC

Freeze frame

Freeze frame

Home

Refresh

Clear

Return