


Infinix HOT 12 PLAY





VCI-9090126821 connected

CHANGAN(V2.95) > CHANGAN > CS55 Series > NEW CS55PLUS > DCT 270 > Diagnostic data version > Real

P12A298 Clutch overheat protect: Clutch temperature too high

P124398 Clutch1 temperature too high: Clutch1 temperature too high



Infinix HOT 12 PLAY

