

QUALITY INFORMATION REPORT

1	ISSUE NO.	VEN2024001
2	DATE	11/06/2024
3	COUNTRY	VENEZUELA

CHARACTERISTIC				
Quality Type	5	<input checked="" type="checkbox"/> Critical	<input type="checkbox"/> Mass	<input type="checkbox"/> Common
Fault Frequency	6	<input checked="" type="checkbox"/> Frequent	<input type="checkbox"/> Occasional	<input type="checkbox"/> For the first time
Fault Quantity	7	Fault Rate		

FAULT INFORMATIONS							
Failed Position and Fault Reason Type	8	9	10	11	12	13	
	System	Parts Quality	Appearance Quality	Assemble Quality	Oth Prob		
		Chassis	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		Electric Equipment	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		Body	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	Power Train	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	A/C	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

FAILURE CONDITIONS									
14	15	16	17	18	19	20	21		
Road Conditions	Speed (km/h)	Time of Failure	Rainy Conditions	Purpose	Loading Status				
<input checked="" type="checkbox"/> Downtown	<input type="checkbox"/> >80km/h	<input checked="" type="checkbox"/> Starting	<input type="checkbox"/> Light Rain	<input checked="" type="checkbox"/> Passenger transport	<input checked="" type="checkbox"/> One Person	<input type="checkbox"/> ON			
<input type="checkbox"/> Suburb	<input checked="" type="checkbox"/> >40km/h	<input type="checkbox"/> After Start	<input type="checkbox"/> Heavy Rain	<input type="checkbox"/> Household	<input type="checkbox"/> Two Person	<input checked="" type="checkbox"/> OFF			
<input type="checkbox"/> Highway	<input type="checkbox"/> <40km/h	<input type="checkbox"/> Start Up	<input type="checkbox"/> After Car	<input type="checkbox"/> Rent	<input type="checkbox"/> Three Person				
<input type="checkbox"/> Mountain		<input type="checkbox"/> Accelerate	<input type="checkbox"/> Washing	<input type="checkbox"/> Long distance transport	<input type="checkbox"/> Four Person				
<input type="checkbox"/> Uphill		<input type="checkbox"/> Uniform	<input type="checkbox"/> After Rainy	<input type="checkbox"/> Others	<input type="checkbox"/> Five Person				
<input type="checkbox"/> Downhill		<input type="checkbox"/> Decelerate	<input type="checkbox"/> Run in Deep water		<input type="checkbox"/> Over loading				
<input type="checkbox"/> Curves		<input type="checkbox"/> Brake	<input type="checkbox"/> After Running in the Deep Water						
<input type="checkbox"/> Dirt		<input type="checkbox"/> Intermittence							
<input type="checkbox"/> Uneven		<input type="checkbox"/> Rest							
<input type="checkbox"/> Level		<input type="checkbox"/> After High Speed							
<input type="checkbox"/> Gravel		<input type="checkbox"/> Turn Left							
<input type="checkbox"/> Snow		<input type="checkbox"/> Turn Right							
		<input type="checkbox"/> Traffic Jam							

PROBLEM DESCRIPTION(SYMPOM)	
22	UNIDAD NO ENCIENDE, BOMBIN LE FUE REEMPLAZADO PERO SIGUE SIN ENCENDER

ANALYSIS AND INSPECTION	
23	=====

METHOD AND SUGGESTION	
24	AMERITA REPARACION DE MOTOR Y REEMPLAZO DE SUS COMPONENTES INTERNOS.


END-CUSTOMER REQUEST	
25	LISTA DE ELEMENTOS AFECTADOS

LUEGO DE HACERNOS SABER SU MOLESTIA, NOS INDICA QUE SI DESEA SER REPARADO EL MOTOR BAJO LO AUTORIZADO POR PLANTA




PICTURE

PICTURE



PICTURE



PICTURE

PICTURE



PIC



PICTURE



PICTURE



PICTURE



PICTURE



PICTURE



DESCRIPTION	VIDEO	VIDEOS DESCRIPTION	FAULT MOMENT (SEG)
C1 ANILLO1: 028 C1 ANILLO 2: 022 C1 ANILLO 3: 035 SE ENCUENTRA FUERA DE TOLERANCIA			
C2 ANILLO 1: 021 C2 ANILLO 2: 026 C2 ANILLO 3: 035			
al remover las tapas las empackaduras en su defecto pierden su forma. Por lo que amerita su reemplazo			
C3 ANILLO 1: 026 C3 ANILLO 2: 025 C3 ANILLO 3: 035			
C4 ANILLO 1: 025 C4 ANILLO 2: 085 C4 ANILLO 3: 025			
CONCHAS DE BIELA Y BANCADA TIENEN DESGASTES SE APRECIA RAYADURAS O DESGASTE			
SE APRECIA DESGASTE			

DESCRIPTION
anillos presentan desgastes haciendo que su funcion no se correcta

DESCRIPTION

LOS EMSAMBLES TIENE RAYADURAS Y DESGASTES

DESCRIPTION

LOS EMSAMBLES TIENE RAYADURAS Y DESGASTES

DESCRIPTION