

ANDINA MOTOR'S, C.A

SERVICIO

FECHA: 19/08/2024

INFORME DE FALLA DE UNIDADES

Propietario: EUCLIDES SEGUNDO LUGO PERAZA

VIN: LSCBBZ2T1MG612788 **Kilometraje:** 64698

Placa: A71DP5M

Reporte de cliente:

VEHICULO PRESENTA CONSUMO DE ACEITE
VEHICULO TIENE BOTE DE ACEITE

Diagnostico:

SE REALIZA REVISION Y LA UNIDAD PRESENTA FUGA DE ACEITE POR LA VARILLA DE ACEITE

SE MIDE COMPRESIO Y SE OBTIENE:

CIL 1:300

CIL2:200

CIL3:200

CIL4:240

SE DESMONTA SE OBSERVA

- CILINDRO 2 Y 3 ANILLOS PARTIDOS
- CILINDRO 1 Y 4 ANILLOS ENFRENTADOS, DESGASTE CAMISA
- CIGÜEÑAL: MUÑEQUILLA 3 BANCADA CON DESGASTE Y MUÑEQUILLA 3 BIELA CON DESGASTE EXCESIVO
- PISTONES CON SEÑAL DE SOBRECIENTAMIENTO
- BOMBA DE ACEITE Y VACIO CON SEÑAL DE DESGASTE

PIEZAS PARA REPARACION DE MOTOR:

- CIGÜEÑAL
- ENSAMBLES DE BANCADA
- CONCHAS DE BIELA Y BANCADA
- BOMBA DE ACEITE
- BOMBA DE VACIO
- CAMISAS
- ANILLOS DE BRONCE
- PISTONES
- JUEGO DE EMPAQUES
- JUEGO DE ANILLOS

HEBEI CHANGAN AUTOMOBILE CO., LTD

VIN: LSCBBZ2T1MG612788

Trademark: CHANA Made in China

Model: SC1035SPCD5

Engine model: JEAD25Q5A

Engine displacement: 2499ml

Engine the max.net power: 93kW

Total mass: 3120kg Seats: 5

Manufacturing date: 2020-10-20



HEBEI CHANGAN AUTOMOBILE CO., LTD

VIN:LSCBBZ2T1MG612788

Trademark: CHANA Made in China

Model: SC1035SPCD5

Engine model: JE4D25Q5A

Engine displacement: 2499ml

Engine the max.net power: 93kW

Total mass: 3120kg Seats: 5

Manufacturing date: 2020-10-20





REPUBLICA BOLIVARIANA DE VENEZUELA

CAPRI
A64AU2T

TRUJILLO